



1940'S EPIPHONE ELECTAR ZEPHYR

- NOTES.
1. THE FIELD COIL SPEAKER HAS BEEN REPLACED AND A 10H CHOKE ADDED TO THE POWER SUPPLY WHERE THE FIELD COIL WOULD NORMALLY WIRE TO.
 2. THE STANCOR 6014-P P.T. WAS REPLACED WITH A HAMMOND UNTIL ANOTHER STANCOR CAN BE FOUND.
 3. THE .047 TONECAP CONNECTION WAS MOVED FROM BEFORE TO AFTER THE VOLUME POT.

DRAWN & MODIFIED BY; MARK SCHMITT-989-697-3558
 FROM AN AWESOME CIRCUIT BY: EPIPHONE, NY.
 THANKS TO JESS AT OLIVER SOUND AND GEORGE AT
 METROAMP.COM FOR THE TECHNICAL HELP AND PARTS.

